

Release Notes

EWS7926EFP

Ver. v1.07.23_c1.9.21

Revision History

Revision	Date	Reason of Changes
v1.07.23_c1.9.21	Nov 30, 2018	Fix update

Change Log

Notice: APs upgraded to c1.9.x version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v1.07.23_c1.9.21
Type	Description
New Feature	N/A
Change	N/A
Fix	<ol style="list-style-type: none">1. Enclose fix for error message upon trying to access Controller Log Settings web page where it displays Sorry there was an error 404 Not Found.2. Enclose fix to allow other switch to find EWS7926E, EWS7926EFP via topology view.