

# **Release Notes**

**EWS355AP**

**Ver. v3.6.6\_c1.9.30**

## Revision History

Revision	Date	Reason of Changes
v3.6.6_c1.9.30	Nov 8, 2019	Change and fix update

## Change Log

**Notice:** APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.6.6_c1.9.30
Type	Description
New Feature	N/A
Change	1. Support Post Association mechanism for band steering.
Fix	1. Resolve captive portal session timeout issue. 2. Fix bridge error with management VLAN and captive portal.