

Release Notes

EWS355AP

Ver. v3.6.8_c1.9.30

Revision History

Revision	Date	Reason of Changes
v3.6.8_c1.9.30	Jan 17, 2020	Change update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.6.8_c1.9.30
Type	Description
New Feature	N/A
Change	1. Revert RSSI Threshold function. 2. Remove auto detect time zone function on GUI and EnWifi.
Fix	N/A