

Release Notes

ENS620EXT

Ver. v3.5.1_c1.9.04

Revision History

Revision	Date	Reason of Changes
v3.5.1_c1.9.04	Sep 11, 2018	Change and Fix update

Change Log

Notice: Before upgrade to v3.5.1_c1.9.04, please first upgrade the middle firmware first.

F/W Version	v3.5.1_c1.9.04
Type	Description
New Feature	N/A
Change	1. Update CAPWAP version to c1.9.04
Fix	1. Fix L2-isolation doesn't work properly when VLAN enabled.