

Release Notes

EMR3500

Ver. 1.0.7

Revision History

Revision	Date	Reason of Changes
v1.0.7	Aug 30, 2019	Change and Fix update

Change Log

F/W Version	v1.0.7
Type	Description
New Feature	1. N/A
Change	1. Support 802.11v in Band Steering function.
Fix	1. Solve the issue that master device takes longer time to check the new firmware on the server and cause timeout on EnMesh android version.