

## 檢驗報告

報告編號： US/2011/50479A-01

日期： 2011年06月07日 頁數： 1 of 2



久道科技股份有限公司

台北市信義區西村里信義路5段5號2C-06室

以下測試之樣品係由供應廠商所提供及確認：


**產品名稱：** 健康車室殺菌機  
**採樣點名稱：** 01 Toyota Camry(9282-PP)健康測試殺菌器使用前  
 02 Toyota Camry(9282-PP)健康測試殺菌器使用後  
**申請廠商：** 久道科技股份有限公司  
**採樣地點：** 中壢車美仕公司/桃園縣中壢市吉林路一號  
**採樣人員：** 林彥坊、張鈺泉  
**送樣日期：** 2011年05月30日  
**測試日期：** 2011年05月31日

**測試項目：** 1.空氣中甲醛含量檢測  
 2.空氣中甲苯含量檢測  
 3.空氣中總落菌數檢測

**測試方法：** 1.以 XAD-2 吸附管採樣 30 分鐘後，以氣相層析儀火焰離子化偵測器(GC/FID)分析。  
 2.以活性碳管採樣 30 分鐘後，以氣相層析儀火焰離子化偵測器(GC/FID)分析。  
 3. 利用培養皿吸收採樣空氣內之菌落數 30 分鐘後，採樣完畢攜回培養皿放置恆溫培養箱(30°C)中 48 小時後計數。

**測試結果：**  
 -請見下頁-

Signed for and on behalf of  
SGS Taiwan Ltd.

  
 River Lee  
 Asst. Manager



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company.除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。  
 This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at [http://www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

檢驗報告

報告編號： US/2011/50479A-01

日期： 2011年06月07日 頁數： 2 of 2



久道科技股份有限公司  
台北市信義區西村里信義路5段5號2C-06室

測試結果：

測試項目	CAS NO.	測試結果		檢測極限	單位
		Toyota Camry(9282-PP) 健康測試殺菌器使用前	Toyota Camry(9282-PP) 健康測試殺菌器使用後		
甲醛	000108-88-3	N.D.	N.D.	24.0	ppbv
甲苯	000050-00-0	N.D.	N.D.	8.40	ppbv
總落菌數	---	19	3	1.0	CFU

\*使用前：樣品啟動前 30 分鐘採樣

使用後：啟動 1.5 小時後採樣

- 備註：1.本報告不得分離，分離使用無效。  
2.低於方法偵測極限之測定值以 " N.D. " 表示。

\*\*\*報告結尾\*\*\*